SS-177 % Rev ed 1-71

## WEST VIRGINIA SEPTIC TANK INSPECTION FORM

Vendleton Co. Health Department Installation Permit No.
Name of Owner Richard B. Gilstrap
Address Rt. 1 Box 453-H Stuarts Draft Va. 24477
Property Address Sugar From W.Va.
DESCRIPTION & NUMBER OF UNITS SERVED
Type Facility Served Cahin No. Water Closets /
Lot Size sq. ft. Area suitable for sewage disposal installation sq.ft
Source of Water Supply perposed well No. Lavatories
No. Bedrooms No. Showers or Tubs No. Baths
No. Garbage Grinders O No. Automatic Washers O
SEPTIC TANK
Material <u>(rmrnf</u> Length <u>8'6"</u> x Width <u>4'8"</u> x Depth <u>5'8"</u> = cubic feet
Liquid Depth 4.5 ft. Liquid Capacity 1,000 gal.
Distance to: Dwelling 18' Water Supply 50'+ Nearest Property Line 50'+
SOIL ABSORPTION SYSTEM
Type Drain Line Material 4"plastic Trench Width 36 Inches
Trench Depth $20 t_0 30$ Inches Total Absorption area in Trench Bottom $600$ sq. ft.
Diameter of Drain Line 4 Inches Type Filter Media # 6 GraveL
No. of Drain Lines $3$ Depth Filter Media Under Drain Line $6$ Inches
Length of Each Line 60',60',80', ft. Depth Filter Media Over Drain Line 2 in
Distance of Disposal Field to: (a) Dwelling 40
(b) Water Supply 100't (c) Nearest Property Line 50'
An inspection of the septic tank system described herein disclosed that said system (MEETS, DOES NOT MEET) the minimum standards established by the West Virginia State Department of Health.
11-4-94 Lennis a. Meadows Sanitarian Tristabler

SKETCH OF SYSTEM TO BE DRAWN ON BACK

Note: Copy of this inspection report must be given to owner and the original filed in the Health Department files. PERMANENT RECORD - DO NOT DESTROY.

Way Drive camper Trailer tabin <u>.</u> 4,087